



Job details

Report type	Print Production-Report
Job name	Calibration test job v1
Number of measurements	17
Customer	
Date	05/28/2019 12:44 PM
Producer	Offset 3000
Assessment	 Pass, score 82%

Instrument and scoring setup

Targetset	ISO 12647-2 2013 Coated
Scoring	ISO 12647 - 3 TVI
Backing	Black
Illuminant / Observer / Condition	D50 / O2 / M0

Summary

	Print / Target [L a b]			D	ΔE / Tol	ΔE	⊞
Black	17.5 / 16.0	1.1 / 0.0	3.8 / 0.0	1.70	4.4 / 4	60%	100%
Cyan	55.2 / 55.0	-37.6 / -35.0	-49.1 / -51.0	1.49	3.4 / 4	100%	78%
Magenta	50.4 / 47.0	75.1 / 73.0	-5.6 / -4.0	1.34	4.5 / 4	60%	100%
Yellow	88.4 / 87.0	-4.9 / -4.0	90.5 / 91.0	1.25	2.6 / 5	100%	78%
Red (M+Y)	49.2 / 46.0	67.9 / 67.0	45.9 / 45.0	1.45	3.8 / 9	100%	 0%
Green (C+Y)	48.7 / 49.0	-68.7 / -63.0	24.3 / 25.0	1.44	6.2 / 9	100%	
Blue (C+M)	26.0 / 24.0	16.0 / 20.0	-48.3 / -45.0	1.40	5.7 / 8	100%	
Paper	95.7 / 93.0	0.9 / 1.0	-2.7 / -5.0	0.05	3.6 / 4	100%	

Comments

Signed

	Place and date	Sign