


Job details

Report type	Print Production-Report
Job name	Calibration test job v1
Number of measurements	17
Customer	
Date	05/28/2019 12:44 PM
Producer	Offset 3000
Assessment	 Pass, score 82%

Instrument and scoring setup

Targetset	ISO 12647-2 2013 Coated
Scoring	ISO 12647 - 3 TVI
Backing	Black
Illuminant / Observer / Condition	D50 / O2 / M0